

 M\_POINT024


Measured X = 2569.5838	Y = 210.1389	Z = 686.3021	Y
Nominal X = 2569.4883	Y = 210.1359	Z = 679.4901	
Dev X = 000.0955	Y = 000.0030	Z = 006.8120	Z X
Tolerance X = 004.0000/-004.0000 Y = 004.0000/-004.0000 Z = 001.2700/-001.2700			

 M\_POINT025

Measured X = 2568.9242	Y = 193.5480
Nominal X = 2569.4883	Y = 193.5053
Dev X = -000.5641	Y = 000.0427
Tolerance X = 004.0000/-004.0000 Y = 004.0000/-004.0000	

 M\_POINT026

M\_POINT029  
Measured X = 2549.1371 Y = 182.9699

 M\_POINT028

M\_POINT027